please copy the attached BMXP file to "D" Disc in the controller computer Then please release the file, you can find the file as follow:



Please click it, you will see follow:

| 👗 AutoCADSetup | | |
|--|---|--------|
| - AutoCut for AutoCAD 2000/2002 | | |
| Install Uninstall | Undetected AutoCAD20 | 900 |
| AutoCut for AutoCAD 2004 | | |
| Install Uninstall | Undetected AutoCAD20 | 0041 |
| - AutoCut for AutoCAD 2005 | | |
| hattoolt for hattoold 2000 | | |
| Install Uninstall Has Installed! Deter | ted AutoCAD2005 | |
| Install Uninstall Has Installed! Deter Y:\各部门\外销专用\BMXP20090806A\PlugIn\Wa | tted AutoCAD2005? | |
| Install Uninstall Has Installed! Deter Y:\各部门\外销专用\BMXP20090806A\PlugIn\We | eted AutoCAD2005 ? edm2005.arx | |
| Install Uninstall Has Installed! Deter Y:\各部门\外销专用\BMXP20090806A\PlugIn\Wa AutoCut for AutoCAD 2006 Install Uninstall | ted AutoCAD2005 dm2005.arx Undetected AutoCAD20 | 006 \$ |

Please click "Uninstall" to delete the old software

Then please click "Install" to install the new software.

Please create a shortcut icon on the desktop for "Wirecut.exe ", which you can find in the BMXP file.



Please test the machine, if everything is OK, please delete it old shortcut icon

